



Inspection Convertible Gocarz

Gocarz France Clement / Mazda Mx5 / CV53 OFB

Terminée

Résultat	88.89%	Éléments échoués	0	Actions	0
Réalisé le / Conducted on :			18th May, 2021 10:00 AM BST		
Nom de l'inspecteur / Inspector's name :			Gocarz France Clement		
Localisation / Location :			2-20 Lake St, Great Moor Stockport Angleterre SK2 Royaume-Uni (53.390043329621555, - 2.1398663930501343)		
Immatriculation véhicule / Car registration # :			CV53 OFB		
Marque & Modèle de véhicule / Car's Make & Model			Mazda Mx5		

Carrosserie / Bodywork

Condition de la carrosserie / Bodywork condition ?

Très bien / Very good

Qqs impacts de gravillons sur le pare-chocs av et le capot.

Qq micro rayures de surfaces à divers endroits

Aucune imperfection majeure



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12




Photo 13




Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22




Photo 23



Photo 24




Photo 25



Photo 26



Photo 27



Photo 28



Photo 29




Photo 30



Photo 31



Photo 32




Photo 33




Photo 34




Photo 35




Photo 36





Photo 37

Photo 38

Photo 39

Photo 40

Photo 41

Photo 42



Photo 43



Photo 44




Photo 45




Photo 46




Photo 47



Photo 48



Photo 49




Photo 50



Photo 51



Photo 52




Photo 53




Photo 54



Photo 55



Photo 56




Photo 57



Photo 58



Photo 59



Photo 60




Photo 61




Photo 62




Photo 63



Photo 64



Photo 65



Photo 66



Photo 67




Photo 68




Photo 69




Photo 70




Photo 71




Photo 72



Photo 73




Photo 74




Photo 75




Photo 76



Photo 77



Photo 78

Trace d'accident / Sign of accident ?

non visible

Véhicule repeint / Resprayed vehicle ?

non visible

Le coffre souffre-t-il de déformations, réparations ou corrosion / Boot showing signs of deformations, repairs or corrosion ?

No




Photo 79



Photo 80



Photo 81



Photo 82



Photo 83



Photo 84




Photo 85




Photo 86




Photo 87



Photo 88

Etat de la capote / Condition of soft or hard top ?

Très bien / Very good



Photo 89



Photo 90



Photo 91



Photo 92

Soubassements, Chassis / Underbody

Corrosion du châssis / Chassis corrosion ?

Très bien / Very good

Ligne d'échappement changée

Protection antirouille appliquée

Un par chaleur présente néanmoins de la rouille perforante




Photo 93



Photo 94




Photo 95




Photo 96




Photo 97




Photo 98




Photo 99




Photo 100




Photo 101




Photo 102




Photo 103




Photo 104




Photo 105




Photo 106



Photo 107




Photo 108




Photo 109



Photo 110




Photo 111



Photo 112




Photo 113




Photo 114




Photo 115




Photo 116



Photo 117




Photo 118




Photo 119




Photo 120



Photo 121




Photo 122




Photo 123




Photo 124




Photo 125




Photo 126




Photo 127




Photo 128






Photo 129



Photo 130



Photo 131



Photo 132



Photo 133




Photo 134



Photo 135




Photo 136




Photo 137



Photo 138




Photo 139




Photo 140



Photo 141



Photo 142

Trace de fuite d'huile / Sign of oil leak?

non visible

Consommables & Fluides / Consumables & Fluids

100%

Roue de secours - galette en bon état / Spare wheel in good condition ?

Yes

Etat des pneus avant / Front tyres condition :

OK

Pneus Toyo neufs




Photo 143



Photo 144



Photo 145



Photo 146

Pneus avant identiques / Front matching tyres ?

Yes

Etat des pneus arrière / Rear tyres condition :

OK

Pneus Toyo neufs




Photo 147



Photo 148



Photo 149



Photo 150

Pneus arrières identiques / Rear matching tyres ?

Yes

Freins avant / Front brakes

OK



Photo 151




Photo 152



Photo 153




Photo 154

Freins arrière / Rear brakes

OK




Photo 155




Photo 156




Photo 157




Photo 158

Liquide de frein / Brake fluid

OK

Etat des courroies / Belts condition (timing & auxiliary):

OK

Distribution neuve

Huile moteur (état - niveau) / Engine oil (condition - level)

OK




Photo 159




Photo 160



Photo 161

Liquide de refroidissement (état - niveau) / Coolant (condition - level)

OK

Huile de BV (état - niveau) / Gearbox oil (condition - level)

OK

Mécanique / Mechanic

72.73%

Baie moteur accessible / Engine bay accessible ?

Yes

Etat général baie moteur / General condition engine bay ?

Très bien / Very good




Photo 162




Photo 163




Photo 164




Photo 165



Photo 166




Photo 167



Photo 168




Photo 169




Photo 170




Photo 171



Photo 172




Photo 173



Photo 174



Photo 175

☒ Vidéo moteur tournant / Video running engine (cold & warm)

☒ Vidéo gaz d'échappement / Video exhaust gas

Diagnostic électronique / Electronic Diagnostic

Code(s) erreur trouvés / Fault code(s) found ?

No



Photo 176



Photo 177



Photo 178

Essai routier / Test drive

Essai routier effectué par l'inspecteur? / Car test driven by inspector personally?

Yes

Conditions	sec / dry ville / town roads 10 - 15 min
Moteur / Engine (Bruits , vibrations, fumées / Noises, vibrations, smoke) :	OK
Transmission (Bruits , vibrations, fumées / Noises, vibrations, smoke) :	OK
Vibration légère du levier de vitesse	
Suspensions (Condition) :	OK
Ressenti direction / Steering wheel abnormal sensations ?	Safe

Etat de l'intérieur / Interior condition ?

Très bien / Very good



Photo 179




Photo 180



Photo 181



Photo 182



Photo 183



Photo 184



Photo 185



Photo 186



Photo 187



Photo 188




Photo 189



Photo 190




Photo 191



Photo 192




Photo 193




Photo 194



Photo 195



Photo 196



Photo 197




Photo 198




Photo 199




Photo 200




Photo 201



Photo 202



Photo 203



Photo 204




Photo 205




Photo 206




Photo 207




Photo 208




Photo 209




Photo 210




Photo 211




Photo 212




Photo 213




Photo 214




Photo 215



Photo 216



Photo 217



Photo 218




Photo 219




Photo 220



Photo 221




Photo 222



Photo 223




Photo 224




Photo 225



Photo 226




Photo 227



Photo 228



Photo 229



Photo 230



Photo 231

Mileage (Miles)

70832

Témoins allumés / Dashboard lights on ?

No

Klaxon fonctionnel / Horn working ?

Yes

Fermeture centralisée fonctionnelle / Central locking working ?

N/A

Fenêtres électriques fonctionnelles / Electric windows working ?

Yes

Réto. électriques fonctionnels / Electric mirrors working ?

N/A

Unité centrale fonctionnelle / Head unit working ?

Yes

Essuis glace fonctionnels / Wipers working ?

Yes

Eclairage fonctionnel / All lights working ?

Yes



Photo 232




Photo 233




Photo 234




Photo 235



Photo 236



Photo 237

Ouverture - Fermeture de toutes les portes / All doors opening - closing ?

Yes

Ceintures de sécurité fonctionnelles / Seatbelts fastening - unfastening ?

Yes

Parre-brise - fenêtres - rétroviseurs intacts / Windshield - windows - mirrors free from cracks ?

Yes

Administratif

100%

Nombre de clefs / Number of keys ?

2

Toutes les clefs fonctionnelles / All keys working ?

Yes

Ecrou antivol présent / Locking nut available ?

N/A

HPI check (base de donnée des assurances) :

N/A

Cat D signifie que le coût des réparations des dommages subits est inférieur au prix argus du véhicule, Cat C le coût des réparations dépasse le prix argus, Cat B le véhicule peut être vendu en pièces détachées uniquement et enfin Cat A, le véhicule ne peut être que détruit.

Correspondance VIN / Matching VIN (chassis, V5, pare-brise / windshield) :

Yes



Photo 238




Photo 239

V5 disponible / Available V5 ?

Yes



Photo 240




Photo 241




Photo 242

Date du dernier CT / Last MOT Test date ?

Moins de 6 mois (Less 6mths)




Photo 243




Photo 244



Photo 245




Photo 246




Photo 247



Photo 248



Photo 249




Photo 250




Photo 251

☒ Carnet d'entretien et-ou factures vérifiés / Service book and-or invoices checked ?

☒ CERFA cession rempli / French certificate of sale filled-up ?

Signature (for inspectors only)

A handwritten signature in black ink, consisting of a large, stylized 'S' shape with a horizontal line crossing it.

18th May, 2021 5:53 PM BST

Annexe



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44



Photo 45



Photo 46



Photo 47



Photo 48



Photo 49



Photo 50



Photo 51



Photo 52



Photo 53



Photo 54



Photo 55



Photo 56




Photo 57



Photo 58



Photo 59



Photo 60



Photo 61



Photo 62



Photo 63



Photo 64



Photo 65



Photo 66



Photo 67



Photo 68



Photo 69



Photo 70



Photo 71



Photo 72



Photo 73



Photo 74



Photo 75



Photo 76



Photo 77



Photo 78



Photo 79



Photo 80



Photo 81



Photo 82



Photo 83



Photo 84



Photo 85



Photo 86



Photo 87



Photo 88



Photo 89



Photo 90



Photo 91



Photo 92



Photo 93



Photo 94



Photo 95



Photo 96



Photo 97



Photo 98



Photo 99



Photo 100



Photo 101



Photo 102



Photo 103




Photo 104



Photo 105



Photo 106



Photo 107





Photo 109

Photo 108



Photo 110



Photo 111



Photo 112



Photo 113



Photo 114



Photo 115



Photo 117



Photo 116



Photo 118



Photo 120

Photo 119



Photo 121



Photo 123



Photo 125



Photo 122



Photo 124



Photo 126



Photo 127



Photo 128



Photo 129



Photo 130



Photo 131



Photo 132



Photo 133



Photo 134



Photo 135



Photo 136



Photo 137



Photo 138



Photo 139



Photo 140



Photo 141



Photo 142



Photo 143





Photo 145

Photo 144



Photo 147

Photo 146



Photo 149

Photo 148



Photo 150



Photo 151



Photo 152



Photo 153



Photo 154



Photo 155



Photo 156



Photo 157



Photo 158



Photo 159




Photo 160



Photo 161



Photo 163



Photo 162



Photo 164



Photo 166

Photo 165



Photo 167



Photo 169



Photo 171



Photo 168



Photo 170



Photo 172



Photo 173



Photo 174



Photo 175



Photo 176



Photo 177



Photo 179



Photo 181



Photo 183



Photo 178



Photo 180



Photo 185



Photo 182



Photo 187



Photo 184



Photo 189



Photo 186



Photo 191



Photo 193



Photo 188



Photo 190



Photo 192



Photo 195




Photo 194



Photo 197



Photo 196



Photo 199



Photo 198



Photo 201



Photo 200



Photo 203



Photo 202



Photo 205



Photo 204



Photo 207



Photo 206



Photo 209



Photo 208



Photo 210



Photo 211



Photo 213



Photo 212




Photo 214



Photo 216



Photo 215



Photo 217



Photo 218



Photo 220



Photo 222

Photo 219



Photo 221



Photo 223



Photo 225



Photo 224



Photo 226



Photo 228



Photo 227



Photo 229



Photo 230



Photo 232



Photo 234



Photo 231



Photo 236



Photo 233



Photo 238




Photo 235

UK Registration Certificate	
4. Vehicle details A. Registration mark: CV53 OFB B. Date of first registration: 01/08/2003 C. Date of first registration in the UK: 01/08/2003 D. Make: MAZDA E. Type: CONVERTIBLE F. Colour: BLUE G. Variant: 1.6 H. Variant description: 1.6 I. Variant description: 1.6 J. Variant description: 1.6 K. Variant description: 1.6 L. Variant description: 1.6 M. Variant description: 1.6 N. Variant description: 1.6 O. Variant description: 1.6 P. Variant description: 1.6 Q. Variant description: 1.6 R. Variant description: 1.6 S. Variant description: 1.6 T. Variant description: 1.6 U. Variant description: 1.6 V. Variant description: 1.6 W. Variant description: 1.6 X. Variant description: 1.6 Y. Variant description: 1.6 Z. Variant description: 1.6	
5. Registered keeper A. Name: MAZDA MOTOR CORPORATION B. Address: MAZDA MOTOR CORPORATION C. Address: MAZDA MOTOR CORPORATION D. Address: MAZDA MOTOR CORPORATION E. Address: MAZDA MOTOR CORPORATION F. Address: MAZDA MOTOR CORPORATION G. Address: MAZDA MOTOR CORPORATION H. Address: MAZDA MOTOR CORPORATION I. Address: MAZDA MOTOR CORPORATION J. Address: MAZDA MOTOR CORPORATION K. Address: MAZDA MOTOR CORPORATION L. Address: MAZDA MOTOR CORPORATION M. Address: MAZDA MOTOR CORPORATION N. Address: MAZDA MOTOR CORPORATION O. Address: MAZDA MOTOR CORPORATION P. Address: MAZDA MOTOR CORPORATION Q. Address: MAZDA MOTOR CORPORATION R. Address: MAZDA MOTOR CORPORATION S. Address: MAZDA MOTOR CORPORATION T. Address: MAZDA MOTOR CORPORATION U. Address: MAZDA MOTOR CORPORATION V. Address: MAZDA MOTOR CORPORATION W. Address: MAZDA MOTOR CORPORATION X. Address: MAZDA MOTOR CORPORATION Y. Address: MAZDA MOTOR CORPORATION Z. Address: MAZDA MOTOR CORPORATION	
6. Changes to current vehicle A. Date of change: 01/08/2003 B. Date of change: 01/08/2003 C. Date of change: 01/08/2003 D. Date of change: 01/08/2003 E. Date of change: 01/08/2003 F. Date of change: 01/08/2003 G. Date of change: 01/08/2003 H. Date of change: 01/08/2003 I. Date of change: 01/08/2003 J. Date of change: 01/08/2003 K. Date of change: 01/08/2003 L. Date of change: 01/08/2003 M. Date of change: 01/08/2003 N. Date of change: 01/08/2003 O. Date of change: 01/08/2003 P. Date of change: 01/08/2003 Q. Date of change: 01/08/2003 R. Date of change: 01/08/2003 S. Date of change: 01/08/2003 T. Date of change: 01/08/2003 U. Date of change: 01/08/2003 V. Date of change: 01/08/2003 W. Date of change: 01/08/2003 X. Date of change: 01/08/2003 Y. Date of change: 01/08/2003 Z. Date of change: 01/08/2003	
7. Declaration A. I declare that the information provided is true and correct. B. I declare that the information provided is true and correct. C. I declare that the information provided is true and correct. D. I declare that the information provided is true and correct. E. I declare that the information provided is true and correct. F. I declare that the information provided is true and correct. G. I declare that the information provided is true and correct. H. I declare that the information provided is true and correct. I. I declare that the information provided is true and correct. J. I declare that the information provided is true and correct. K. I declare that the information provided is true and correct. L. I declare that the information provided is true and correct. M. I declare that the information provided is true and correct. N. I declare that the information provided is true and correct. O. I declare that the information provided is true and correct. P. I declare that the information provided is true and correct. Q. I declare that the information provided is true and correct. R. I declare that the information provided is true and correct. S. I declare that the information provided is true and correct. T. I declare that the information provided is true and correct. U. I declare that the information provided is true and correct. V. I declare that the information provided is true and correct. W. I declare that the information provided is true and correct. X. I declare that the information provided is true and correct. Y. I declare that the information provided is true and correct. Z. I declare that the information provided is true and correct.	



Photo 237



Photo 239




Photo 240




Photo 242




Photo 244

Photo 241

Record of Owner's Details

Owner's Details

Name: **H.G. BRYER & SONS LTD.**
Address: **POST OFFICE GARAGE
DRYSLWYN, CARMARTHEN
CAIRNS, SA32 8GX
Tel: (01558) 668 237 / 668 306**
Postcode: **mazda**

Second Owner's Details

Name: **MR A. AGE - HARRIS**
Address: **6 CLOS Y DERI
NANTGARWIDG**
Postcode: **SA32 7LF**

Third Owner's Details

Name:
Address:
Postcode:

Fourth Owner's Details

Name:
Address:
Postcode:

your dealer will send you a copy of this schedule of inspection by

confirmation that the inspection has been completed is shown below.

Name of Mazda Dealer: **H.G. BRYER & SONS LTD**
Date P.D.I. Completed: **6th SEPTEMBER 2003**

The pre-delivery inspection has been completed in accordance with the appropriate checklist.

Signed for Mazda Dealer:
Dealer's Stamp: **H.G. BRYER & SONS LTD.
POST OFFICE GARAGE
DRYSLWYN, CARMARTHEN
CAIRNS, SA32 8GX
Tel: (01558) 668 237 / 668 306
mazda**

The section which follows is the record of the service work carried out on your Mazda by your Mazda dealer.

Photo 246

Photo 243

mazda

Date Completed: **8/6/18** Mileage: **65449.**

Signature:
Repair Order Number:
Dealer's Stamp: **HIGH LANE
113-113 Buxton Road
High Lane Village
Stockport, SK6 8DX
VAT REG No: 811 7157 85
CAR SALES: 01663 763355
TYRES & EXHAUSTS: 01663 764566**

mazda

Date Completed: **5-5-21** Mileage: **70879.**

Signature:
Repair Order Number: **TIMING BELT + GUIDES (Lubricants)**
Dealer's Stamp: **LMC AUTOS
Lake Street, Great Mor
Stockport SK2 7NU
Tel: 0161 483 9760**

Photo 245

mazda

Service Record

Mazda Model: **MAZDA MX-5 1.8i Sport with Sat Nav**
Vehicle Identification Number: **JMZNBI8P600314942**

Date of first Registration: **30th SEPTEMBER 2003** Colour Code: **Supreme Blue**

Registration Number: **CV53** OFB Key Number:
Engine Capacity: **1800** Engine Number:
Transmission Type: **6 SPEED Manual**

Dealer's Stamp: **H.G. BRYER & SONS LTD.
POST OFFICE GARAGE
DRYSLWYN, CARMARTHEN
CAIRNS, SA32 8GX
Tel: (01558) 668 237 / 668 306
mazda**

Please ensure you present this booklet to your Mazda dealer so that your service can be recorded.

Photo 248

Mazda

Date Completed 26-4-2011 Mileage 26171

Signature [Signature]

Repair Order Number

Dealer's Stamp

Chapel Garage
Hayfield Road
Chapel-on-le-Frith
High Peak SK23 0JL
Tel: 01298 812139
MOT STATION
No 165187

Date Completed 25/6/2012 Mileage 28465

Signature [Signature]

Repair Order Number

Dealer's Stamp

Chapel Garage
Hayfield Road
Chapel-on-le-Frith
High Peak SK23 0JL
Tel: 01298 812139
MOT STATION
No 165187

Photo 247

INVOICE

FROM: **SM AUTOS**
Unit E3, Enterprise Centre 12
Ford Street
Stockport SK3 0BT
Tel: 0161 480 7171

TO: CLARE BURLAND

INVOICE DATE: 2-3-21 ORDER NO: MAZDA NYS TERMS: CVS30FB (76.835)

QUANTITY	DESCRIPTION	UNIT PRICE	AMOUNT
-	BATTERY DRAIN - REPLACE BATTERY		
-	MOT FAIL - RIDE COIL SPRINGS SEVERELY CORRODED, V/S PL		
-	REPLACE W/S & D/S RIDE SUSPENSION ROL SPRINGS		
-	CUT OUT ROTTED METAL IN W/S OVER HILL		
-	FABRICATE NEW SILL SECTION & WELD INTO CAR		
-	SEAL, STONE CHIP PROTECT ETC		
-	FIT SENSITIVE NEGATIVE CATHODE BATTERY CONNECTION		
	PAIRTS		
	COIL SPRINGS	41.55	82.66
	MARIA BATTERY		79.12
	DISCARDING BATTERY COVER		9.99
	WELDING MATERIALS		15.00
	MOT		35.00
	LABOUR		240.00
	SUB TOTAL		481.77
	VAT		
	TOTAL DUE		481.77

SPECIAL INSTRUCTIONS: 54504019
01-03-21 SM AUTOS

PAID 03/03/2021

Photo 250

Mazda

Date Completed 4-10-04 Mileage 14887

Signature D. James

Repair Order Number 2098

Dealer's Stamp

H. G. Bryer & Sons Ltd
Post Office Garage
Dryslwyn
Carmarthen SA31 8QX
Tel: 01558 668237
Dealer No. 801

Date Completed 6-12-05 Mileage 9779

Signature D. James

Repair Order Number 5893

Dealer's Stamp

H. G. Bryer & Sons Ltd
Post Office Garage
Dryslwyn
Carmarthen SA31 8QX
Tel: 01558 668237
Dealer No. 801

Photo 249

Service Booklet

Date Completed: 20/6/2013 Mileage: 32101

Signature: _____

Repair Order Number: _____

Dealer's Stamp: _____

Chapel Garage
Hayfield Road
Chapel-en-le-Frith
High Peak SK23 0JF
Tel: 01298 812130
MOT STATION
No 165187

Service due at 43,000 miles or 7 years whichever occurs first

Date Completed: 22/8/2014 Mileage: 36084

Signature: _____

Repair Order Number: _____

Dealer's Stamp: _____

Chapel Garage
Hayfield Road
Chapel-en-le-Frith
High Peak SK23 0JF
Tel: 01298 812130
MOT STATION
No 165187

Service due at 73,000 miles or 8 years whichever occurs first

25

Photo 251