

Lexus LS

VIN: JTHBL46F605027255

Petrol

2007

Generated on 2023-07-21 15:53



Theft



Odometer



Financial and legal status



Damage



Things to know about Lexus LS 2007

 AI generated

When considering the 2007 Lexus LS, there are a few different options available to consumers in terms of engines and body types.

First, there are two available engines for the 2007 LS: a 4.6-liter V8 and a 5.0-liter V8. The 4.6-liter engine produces 380 horsepower, while the 5.0-liter engine produces 430 horsepower. Both offer smooth acceleration and plenty of power, but the larger engine obviously provides more oomph.

In terms of body type, there are two main options: a standard sedan and a long-wheelbase sedan. The standard sedan offers plenty of cabin space and legroom, as well as a large trunk for storage. The long-wheelbase sedan, on the other hand, offers even more legroom for passengers in the back seat, making it a great choice for those who frequently chauffeur guests.


Other specs to consider include standard features such as keyless entry, leather upholstery, and a premium sound system. Additionally, there are a number of optional features available for the 2007 LS, such as a rearview camera, parking sensors, and a navigation system.

Overall, the 2007 Lexus LS offers a comfortable and reliable ride, with a choice of powerful engines and spacious body types to suit a variety of needs.


This description is AI-generated and has not undergone human review for potential inaccuracies.

Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?


 We didn't find any records that the vehicle was stolen.

Here's what we checked:



Currently wanted as stolen


✓ No record found



Stolen in the past

✓ No record found

Current status unknown





Stolen in the past


✓ No record found


Vehicle has been recovered


Police database stolen vehicle check completed in:


 United Kingdom

 Slovakia

 Sweden


 Canada


 Romania


 Czechia

Odometer

Are there signs of mileage roll backs or discrepancies?

 Last known mileage: 167,079 mi

 17 mileage records found



Odometer records

2007-01	9 mi
2010-03	62,425 mi
2011-04	96,322 mi
2012-05	112,800 mi
2013-06	114,091 mi
2014-06	126,574 mi
2015-04	131,741 mi
2016-04	138,505 mi
2017-03	144,637 mi

Odometer records

2018-06	146,442 mi
2019-05	149,693 mi
2020-05	152,959 mi
2021-05	155,442 mi
2021-06	155,479 mi
2022-02	157,465 mi
2022-07	166,965 mi
2023-07	167,079 mi

Financial and legal status

Has the vehicle passed its technical inspections? Does it have property rights restrictions or outstanding loans?



Tech inspection is valid

Legal



MOT (technical inspection)

Passed 2023-07

United Kingdom

Has successfully passed technical inspection

Valid until 2024-07

- Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Windscreen damaged but not adversely affecting driver's view
Stone chip (3.2 (a) (i))



Scrap

✓ No record found

No record that vehicle was marked as scrapped



Exported

✓ No record found

No export records found



Imported

✓ No record found

No import records found

Outstanding finance



Lease

✓ No record found

No data available on outstanding loan or finance agreement



Operating-lease

✓ No record found

No record of vehicle being on an operating-lease



Unit-stocking

✓ No record found

No record of vehicle being under unit-stocking finance

Damage

Has this vehicle been damaged in the past? What was the value of the damages?



No damage records found

Damage records



Occasional inaccuracies can occur, especially when checking older vehicles. Illegitimate mechanical garages may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Emissions

How much CO₂ emissions do vehicles of this model/year produce?



Vehicle CO₂ emissions: 261 g/km

CO₂ emissions

Up to 100

101 - 120

121 - 140

141 - 165

166 - 185

186 - 205

206 - 225

Emission CO₂ g/km

Your vehicle CO₂ emission

261 g/km Tax band **M**

Specs & equipment

What specs and equipment are on record for this vehicle?



Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications



Make
Lexus



Model
LS



Variant
LS 460



Body Type
Sedan



Manufacture year
2007



Powertrain displacement
4.6 l



Fuel type
Petrol



Gearbox type
Automatic



Engine description
4.6L PETROL



Engine Code
1UR-FSE

Equipment

REAR SEAT ADJUSTER

SLIDE (POWER), MID CONTROL, RETURN

SEAT MATERIAL

SEMI ANILINE LEATHER

REGULATION COMPLIANCY

WVTA NAME PLATE

SATELLITE RADIO

WITHOUT





DESTINATION PACKAGE	UK	POWER STEERING	EPS + VGRS
FUEL CONSUMPTION STICKER	WITHOUT	MAYDAY SYSTEM	WITHOUT
AUDIO	WITHOUT	SUN SHADE	
		RR DOOR (AUTO) + RR WINDOW (AUTO)	
ANTENNA	WITHOUT	SEAT AIRCONDITIONER	WITH (FR & RR)
SPECIAL UTILITY PACKAGE	WITH (N1)	EMISSION ID PLATE	
		DESTINATION EXCEPT JAPAN	
AIR PURIFIER	WITHOUT	BODY PROTECTION FILM	WITH
DESTINATION PACKAGE (EXCEPT EUROPE)		ENGINE OIL MAINTENANCE INDICATOR	
WITHOUT		WITH	

Timeline

26 records found

The timeline of records for this vehicle

Latest records

<div>2007-01</div> <div> Country unknown</div>	<div> Was manufactured</div> <div>The country indicates either the location of manufacturing facility, assembly plant or registration address of the manufacturer. The date may be approximate.</div>
<div>2007-03</div> <div> United Kingdom</div>	<div> Was registered</div> <div>The record represents an administrative event. This could be related to a change of ownership, documents, etc</div>

2010-03

 United Kingdom



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2011-04

 United Kingdom



Failed a technical inspection

A failed technical inspection (MOT) was recorded in the indicated country. Unsuccessful emission tests will also fall under the same category.

- Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Offside Rear rear brake juddering severely (3.7.A.5b)
- Offside Front Brake pad(s) wearing thin (3.5.1g)
- Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- front & rear brake disc badly worn
- Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Nearside Rear rear brake juddering severely (3.7.A.5b)
- Nearside Front Brake pad(s) wearing thin (3.5.1g)

2011-04

 United Kingdom



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2012-05

 United Kingdom



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2013-06

 United Kingdom



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2014-06

 United Kingdom



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2015-04

 United Kingdom



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2016-04

 United Kingdom



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2017-03

 United Kingdom



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2018-06

 United Kingdom



Failed a technical inspection



A failed technical inspection (MOT) was recorded in the indicated country. Unsuccessful emission tests will also fall under the same category.

- Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

2018-06

 United Kingdom



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2018-06

 United Kingdom



Ownership changed

The country indicated the geographical location of a documented ownership change or renewal. Please note that some changes may be formal, e.g., end-of-lease transfers and similar.

2018-07

 United Kingdom



Had licence plate changed

This vehicle's licence plate has changed.

From: **WV07BPX** To: **ROG40R**

2019-05

 United Kingdom



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2020-05

 United Kingdom



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2021-05

 United Kingdom



Failed a technical inspection



A failed technical inspection (MOT) was recorded in the indicated country. Unsuccessful emission tests will also fall under the same category.

- Nearside Front Lower Suspension arm pin or bush excessively worn Rear arm (5.3.4 (a) (i))
- Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement Front arm (5.3.4 (a) (i))
- Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement Rear arm (5.3.4 (a) (i))
- Offside Front Position lamp not working (4.2.1 (a) (ii))
- Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear arm (5.3.4 (a) (i))
- Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement Front arm (5.3.4 (a) (i))
- Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement Rear arm (5.3.4 (a) (i))

2021-06

 United Kingdom



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2021-12

 United Kingdom



Had licence plate changed

This vehicle's licence plate has changed.

From: **ROG40R** To: **WV07BPX**

2022-02

 United Kingdom



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.

2022-02

 United Kingdom



Ownership changed

The country indicated the geographical location of a documented ownership change or renewal. Please note that some changes may be formal, e.g., end-of-lease transfers and similar.

2022-03

 United Kingdom



Had licence plate changed

This vehicle's licence plate has changed.

From: **WV07BPX** To: **PIL5794**

2022-06

 United Kingdom



Had licence plate changed

This vehicle's licence plate has changed.

From: **PIL5794** To: **WV07BPX**

2022-07

 United Kingdom



Was on sale

This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country overwrites the vehicle's actual location.

2023-07

 **United Kingdom**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test or emission control test) has been recorded. Both successful and failed instances may be included.